

## Release Note for Vigor2133 Series

Firmware Version:	3.8.9.2
Release Type:	Normal
Applied Models:	Vigor2133/Vigor2133n/Vigor2133ac/Vigor2133Vac/Vigor2133FVac

Vigor2133 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

### New Features

- Add dashboard control page in System Maintenance>>Dashboard Control.

### Improvement

- Improved: Enhanced the security on the web server.
- Improved: The System Up Time in Dashboard can be displayed dynamically.
- Improved: Add the option, Comment, under Wireless LAN(2.4GHz)>>Access Control.
- Improved: Modify the password setting mechanism to display the password strength for Wi-Fi security and user password.
- Corrected: Lack of WAN3 and WAN4 options in WAN>>Internet Access>>DHCP Client Options Status.
- Corrected: An error message of “Authorization Required! Browser not authentication-capable or authentication failed” appeared by clicking the LED icon (USB / QoS / CSM / VPN) on Dashboard under User Mode.
- Corrected: Unable to access into the configuration web page by clicking the interface icon on dashboard.
- Corrected: Unable to do firmware upgrade by Central Management>>AP>>AP Maintenance. After clicking OK, Vigor router would reboot.
- Corrected: Under WAN>>Multi-VLAN, some options (e.g., Open WAN Interface for this Channel, WAN setup, and etc.) for an enabled and selected WAN channel disappeared.
- Corrected: LAN2 option and IP Routed Subnet were not enabled under LAN>>General

Setup. But the IP address for LAN2 and IP Routed Subnet were displayed on the Dashboard with wrong color.

- Corrected: The information in Dashboard, Bind IP to MAC, and View ARP Cache Table was not displayed periodically.

## Known Issue

- None.