

Release Note for Vigor2700Ge/e

Firmware Version: 2.8.4
Release Date: May 5, 2014
Applied Models:
Vigor2700Ge, Vigor2700e

- File and Modem Code
 - (1)For Annex A Model,
 - "v2k7ge_a_284" is used for modem code 121201. (Standard)
 - "v2k7ge_a1_284" is used for modem code 113111.
 - "v2k7ge_a2_284" is used for modem code 131701. (Recommended for UK-SEG)
 - "v2k7ge_a3_284" is used for modem code 1401201. (Recommended for USA or for Glite environment)
 - "v2k7ge_a4_284" is used for modem code 1411301.
 - "v2k7ge_a5_284" is used for modem code 142201.
 - (2)For Annex B Model,
 - "v2k7ge_b_284" is used for modem code 131812. (Standard)
 - "v2k7ge_b1_284" is used for modem code 113112.
 - "v2k7ge_b2_284" is used for modem code 1211202.
 - "v2k7ge_b3_284" is used for modem code 1311302. (Recommended for Germany)
 - "v2k7ge_b4_284" is used for modem code 1401302.
 - "v2k7ge_b5_284" is used for modem code 1411402.
 - "v2k7ge_b6_284" is used for modem code 142112. (Support T1.413 Annex B)
 - "v2k7ge_b7_284" is used for modem code 142402.

New Features

- None

Improvement

- Corrected: Security vulnerability for WLAN reported by CERT.
- Corrected: Solve the buffer leakage problem when handling SNMPv2c "getbulk" request.
- Corrected: A local buffer overwrite problem occurs when "*ip igmp_proxy status*" and "*ip igmp_snoop status*" telnet commands are used.
- Corrected: Can not remove old password after setting new password.

- Corrected: "*ip route add*" telnet command can not work.
- Improved: Change PPP CHAP timeout to 60 seconds.
- Improved: Remove PPPoE MTU size limitation for Vietnam.

Known Issue

- None

Notes

Modifications

- None