

## Release Note for Vigor2710 Series

**Firmware Version: 3.3.5.1**

**Built Date: June 30, 2010**

**Applied Models:**

**Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn**

---

- File and Modem Code

(1)For Annex A Model,

- " v2710\_a\_3351" is used for modem code 211011. (Standard)
- " v2710\_a1\_3351" is used for modem code 211801.
- " v2710\_a2\_3351" is used for modem code 2121501.
- " v2710\_a3\_3351" is used for modem code 2211201.
- " v2710\_a4\_3351" is used for modem code 232201. (Recommended for UK – SEG)
- " v2710\_a5\_3351" is used for modem code 243601.
- " v2710\_a6\_3351" is used for modem code 243701.
- " v2710\_a8\_3351" is used for modem code 244001.
- " v2710\_a7\_3351" is used for modem code 2431301.

(2)For Annex B Model,

- " v2710\_b\_3351" is used for modem code 2111112. (Standard)
- " v2710\_b1\_3351" is used for modem code 2111302. (Recommended for Attel Czech only)
- " v2710\_b2\_3351" is used for modem code 2121302 (recommended for Slovskia only).
- " v2710\_b4\_3351" is used for modem code 214702.
- " v2710\_b5\_3351" is used for modem code 2111312.
- " v2710\_b6\_3351" is used for modem code 215202.
- " v2710\_b7\_3351" is used for modem code 246302.

## New Features

- Support call transfer for DECT (for VDn model only).
- Support user-defined phone number for FXS/DECT.
- Add new function for **VoIP>>DECT** ring button (for VDn model only). DECT phone will ring for 5 seconds after presing the button.
- Add a comment field for giving DECT Handset Name (for VDn model only).

- Be able to change TR-069 CPE Client username and password.

## Improvement

- Corrected: Setting problem on Codecs in **VoIP >> Phone Settings** page.
- Corrected: Page error while setting **service name** or **comment** with '\' in **NAT >> Port Redirection** or **NAT >>Open Ports** page.
- Corrected: Might get reboot problem while doing Call Transfer service.
- Corrected: Save problem occurs for **Interval Time** of **Periodic Inform Settings** in **System Maintenance>>TR-069**.
- Corrected: HTTPS URL (without port) setting in ACS Server URL for TR-069 function doesn't work.
- Corrected: Might get reboot problem while doing some unusual calls.
- Corrected: PPTP passthrough can not work.
- Improved: A problem occurred that different Drayteker DHCP servers will use the same transaction ID.
- Improved: Display error in Caller ID.
- Improved: Modified the telnet command (*arp cache table*) for deleting the ARP entry, from 180 seconds to 40 seconds once ARP cache entry is expired.
- Improved: Reword the "*ip arp setCacheLife*" command.

## Related Information

- Get the document, please visit <http://www.draytek.com.tw/user/PdInfoDetail.php?Id=84#PdInfo>
- Get the new firmware, please visit not ready
- Get the customer service support, please visit <http://www.draytek.com.tw/user/ContactHeadquarters.php>
- Get the regulatory compliance information <http://www.draytek.com.tw/user/AboutRegulatory.php>
- Get information for global partners <http://www.draytek.com.tw/user/Globalpartners.php>

## Known Issue

- None

# Notes

## *Modifications*

- None