

Release Note for Vigor3900 Series

Firmware Version:	1.4.3
Release Type:	Normal
Applied Models:	Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

New Features

- None.

Improvement

- Improved: Improvement related to WebGUI security.
- Improved: Update MAC object oui database.
- Improved: Support DHCP option 121 in WAN DHCP client function.
- Corrected: Support Comma ',' in advanced DHCP options.
- Corrected: Unable to log on to Router via WebGUI because of Open VPN debug log.
- Corrected: VPN Syslog was shown in Others tab instead of VPN tab of Syslog Utility.
- Corrected: VigorACS generated an offline alarm for Vigor router when the router configured to use HTTPS for server URL.
- Corrected: Authentication over LDAP server was failed when the username contained the special character (e.g., '(').

Known Issue

- None