Release Note for Vigor2960

Firmware Version:	1.4.3
Release Type:	Normal
Applied Models:	Vigor2960 Series

Vigor2960, a firewall broadband router with the dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The dual-WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from the subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

> **Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.9 or later.**

New Features

- None.

Improvement

- Improved: Improvement related to WebGUI security.
- Improved: Update MAC object oui database.
- Improved: Support DHCP option 121 in WAN DHCP client function.
- Corrected: Support Comma ',' in advanced DHCP options.
- Corrected: Unable to log on to Router via WebGUI because of Open VPN debug log.
- Corrected: VPN Syslog was shown in Others tab instead of VPN tab of Syslog Utility.
- Corrected: VigorACS generated an offline alarm for Vigor router when the router configured to use HTTPS for server URL.
- Corrected: Authentication over LDAP server was failed when the username contained the special character (e.g., '(').

Known Issue

- None