NO:AP1101-2 V.1

Release Note for Firmware Upgrade Utility

Firmware Version: 3.6.3
Built Date: January 25, 2011
Applied Operation System: Windows XP/Vista/7

New Features

- Support firmware upgrade for Vigor*IPPBX* 3510 model, which needs two firmware files.
- Support configuration file backup/restore for Vigor*IPPBX* 3510 model.

Improvement

- None

Known Issue

- None

Notes

Modifications

- None

Bug Lists

- None