

Release Note for Vigor120 Series

Firmware Version:	3.2.8.1
Release Type:	Critical - Upgrade recommended immediately
Release Date:	February 7, 2017
Applied Models:	Vigor120(V2)

- File and Modem Code

(1)For Annex A Model,

- "v12x_a_v3281" is used for modem code 321311. (Standard)
- "v12x_a1_v3281" is used for modem code 310801.
- "v12x_a2_v3281" is used for modem code 310811.
- "v12x_a3_v3281" is used for modem code 3211201
- "v12x_a4_v3281" is used for modem code 332201(recommended for U.K.).
- "v12x_a5_v3281" is used for modem code 343601.
- "v12x_a6_v3281" is used for modem code 343701 (recommended for Italy).
- "v12x_a7_v3281" is used for modem code 3431301.
- "v12x_a8_v3281" is used for modem code 344001.
- "v12x_a9_v3281" is used for modem code 344101.
- "v12x_a10_v3281" is used for modem code 3471101.

(2)For Annex B Model,

- "v12x_b_v3281" is used for modem code 311112. (Standard)
- "v12x_b1_v3281" is used for modem code 3101212.
- "v12x_b2_v3281" is used for modem code 3101332.
- "v12x_b3_v3281" is used for modem code 311102.
- "v12x_b4_v3281" is used for modem code 346302.

New Features

- None.

Improvement

- Improved: Security improvements including one or more considered critical.

Known Issue

- None

Notes

Modifications

- None