

Release Note for Vigor2862 Series

Firmware Version:	3.9.6.2
Release Type:	Normal
Applied Models:	Vigor2862 / Vigor2862n / Vigor2862ac / Vigor2862Vac / Vigor2862L / Vigor2862Ln / Vigor2862Lac

Vigor2862 series is a VDSL2 router with multi-subnet for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. Besides, “n” and “ac” series have built-in Wireless LAN for wireless connection.

New Features

- None.

Improvement

- Improved: Improve the mesh stability.
- Improved the WiFi security (CVE-2020-26139 to CVE-2020-26145; CVE-2020-24586 to CVE-2020-24588).
- Corrected: An issue of dropping NordVPN tunnel.
- Corrected: An issue of failing to save the Bridge Subnet setting for WAN>>Internet>>LTE .

Version and Modem Code

- "Vigor2862_v3.9.6.2_STD_en.zip" provides Annex A modem code 776d07_772801 and 774307_771801, and Annex B modem code 773306_771502 and 773307_771C02.
- "Vigor2862_v3.9.6.2_MDM1_en.zip" provides Annex A modem code 779517_773F01 and 77B507_775401, Annex B modem code 779B06_774F02 and 779B07_774C12. Recommended for Australia.
- "Vigor2862_v3.9.6.2_MDM2_en.zip" provides Annex A modem code 77B506_775401, 778C06_773F01, and Annex B modem code 779906_774402, 779B06_774C02.
- "Vigor2862_v3.9.6.2_MDM3_en.zip" provides Annex A modem code 77C717_775A11, and Annex B modem code 77C717_775A12.

Known Issue

- None.

Notes

- Vigor router supports the mesh network; however, it is not guaranteed to fit your environment. It might not be available and restricted due to the physical connection, actual environment, signal strength, and excessive interference.
- Remove the simplified APM mechanism, and restore it to full version.