

Release Note for Vigor3220 Series

Firmware Version:	3.9.8.9
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor3220/Vigor3220n

Vigor3220 Series, a broadband router, integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- None.

Improvement

- Improved: Use HTTPS instead of HTTP for DrayDDNS opcode Update.
- Improved: Improve the WiFi Driver Security (CVE-2025 20710, CVE-2025 20715, CVE-2025 20716, CVE-2025 20718, CVE-2025 20719, CVE-2025 20720, CVE-2025 20724, CVE-2025 20736).
- Corrected: An issue which the daylight saving feature did not work.
- Corrected: An issue with dial-out restarted when the dial-in device's Internet connection went out.
- Corrected: An issue with lack of TR-069 parameter for WAN1 VLAN Tag (Configuration>>Internet Access).
- Corrected: An issue which the text in Login Page Setup would not be restored with the factory default settings.
- Corrected: An issue occurred after enabling the DNS filter, where the HTTP port number changed to 80, even if a different number was set.

Known Issue

- None.