

# Release Note for Vigor3900 Series

Firmware Version:	1.5.1.2
Release Type:	Normal
Applied Models:	Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

## New Features

- None.

## Improvement

- Improved: Re-generate the default HTTPS server certificate for fitting the coming new policy of some browsers.
- Corrected: An issue of IPsec VPN stability with multiple WAN interfaces.
- Corrected: An issue of LAN DNS not working for LAN to LAN VPN.
- Corrected: An issue that firewall country object did not block some IP addresses correctly.

## Known Issue

- None.