

Release Note for VigorAP 1060C

Firmware Version:	1.4.10
Release Type:	Critical - Upgrade immediately
Applied Models:	VigorAP 1060C

VigorAP 1060C is a ceiling mount Access Point with PoE for offering power supply and support 1.2Gbps @2.4GHz, and 2.4Gbps @5GHz (11ax).

New Features

- None.

Improvement

- Improved: Improve the Web GUI Security.
- Improved: Password mechanism changed to force admin to change the password from the default password.
- Corrected: An issue with failure to access VigorAP from the Internet.
- Corrected: An issue that 5GHz Auto Channel was not selected from all channels.
- Corrected: An issue with SSID not broadcasting while enabled Fast Transition Roaming 802.11r.
- Corrected: An issue that wireless clients would get other LAN's RA in SLAAC IPv6 environment.
- Corrected: An issue that Auto Channel Filtered Out List on Wireless LAN>>Advanced Setting failed to work.
- Corrected: An issue with failure to remote access VigorAP by port forwarding after upgrading the firmware to 1.4.9.
- Corrected: An issue that VigorAP failed to work with the scheduled WiFi UP/Down profile when it was powered on during the schedule.

Known Issue

- None

Notes

- None.