

Release Note for V3300 Series

Firmware Version: 2.6.3.0
Built Date: August, 18, 2010
Applied Models:
Vigor3300V

New Features

- Support AES192 and AES256 on IPSec phase I.
- Add comment field on IP Filter
- Activate WCF license from WAN

Improvement

- Fixed: NAT session numbers are different between data flow monitor and NAT session table.
- Fixed: Ringing timer error when FXS module is 1005~1008.
- Fixed: An error occurred in changing password on WUI.
- Fixed: Use primary DNS IP to resolve Domain for HTTP Request Detection.
- Fixed: An error occurred in switch link with PC.
- Improved: Display port number on user access log.
- Improved: Add an option to enable and disable SNMP.
- Improved: Adjust TCP and UDP session timeout like other DrayTek products.

Known Issue

- None

Notes

- None