

Release Note for Vigor2925 Series

Firmware Version: 3.8.2

Release Date: September 22, 2015

Applied Models:

Vigor2925, Vigor2925n, Vigor2925n-plus, Vigor2925Vn-plus, Vigor2925F, Vigor2925Fn, Vigor2925ac, Vigor2925Vac

Vigor2925 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Support High Availability (HA).
- Support Internal RADIUS & 802.1x Authentication.
- Support Switch Management.
- Support SSL VPN (LAN to LAN) Tunnel.
- Support PPP authentication method of TACACS+ which can be configured in VPN and Remote Access > PPP General Setup.
- Support Bridge mode and firewall configuration for WAN interface.
- Support Station Number for VigorAP.

Improvement

- Improved: Station mode can be used as additional WAN connection.
- Improved: Improve the function of IPv6 firewall filter.
- Corrected: Unable to open 445 Port as default.
- Corrected: UI Dashboard LED shows Line but it redirects to QoS page (for V model only).
- Corrected: Active True IP DMZ gives wrong subnet mask to DMZ host.
- Corrected: Failed to reboot via WEB configuration page.
- Corrected: 5GHz mixed mode issue.

Known Issue

- The WAN port can not work well with Alcatel I-040G device. The quick solution is to

add another switch between Vigor2925 and Alcatel I-040G.

Notes

Modifications

- None