

Release Note for Vigor2926 Series

Firmware Version:	3.9.0
Release Type:	Normal
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Support data compress / decompress for Central Management, VigorAP.
- Support VigorSwitch P1092/G1080/P2121 which can be managed by Central Management>>Switch.
- Support certificates issued by Let's Encrypt.
- Support OpenVPN.
- Support database encryption for hotspot web portal.
- Support IPv6 for hotspot web portal.

Improvement

- Improved: Support user management on the client authentication by the RADIUS server.
- Improved: Able to enable /disable SNMP1 and SNMP2 on System Maintenance>>SNMP.
- Improved: The open port will be changed as 80 automatically for a while during the process of Let's Encrypt operation.
- Improved: Support to change SSL port number via CLI command.
- Improved: Display the SSID name on Wireless LAN>>Security Settings.
- Improved: Support Vietnam SMS provider.
- Improved: TR-069 login message will not show the model (name) of the router.
- Improved: Add IPsec EAP option for IKEv2 LAN to LAN VPN.
- Improved: Send hotspot log for user login/logout to DrayTek Syslog.
- Improved: Support configurable PPP LCP Echo Request options for solving PPPoE disconnection issue with ISP Viettel.
- Corrected: In HA Hot-Standby mode, DHCPv6 Sync Status failed in the Secondary router.
- Corrected: The router did not clear route advertised from BGP.

- Corrected: Unable to allocate static IP address to IKEv2 VPV client.
- Corrected: Wrong IP address for the subnet mask “/15”. Correct IP address should be “255.254.0.0”.
- Corrected: The firewall did not block traffic to static route networks.
- Corrected: Vigor router ignored Don't Fragment flag in IP header.
- Corrected: Unable to save the WDS security key.
- Corrected: Data quota set on User Management>>User Profile would be reset to zero after re-login.
- Corrected: UPnP and DMZ host did not work properly on Xbox One.

Known Issue

- None.