

Release Note for VigorSwitch Q1070x

| | |
|-------------------|--|
| Firmware Version: | 1.58.1 |
| Release Type: | Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations |
| Applied Models: | VigorSwitch Q1070x |

VigorSwitch Q1070x features five 2.5G Ethernet ports and two SFP ports (10G/2.5G/1G), making it a standard switch that complies with IEEE 802.3u/ab Fast Ethernet and Gigabit Ethernet specifications.

New Features

- Support 802.1Q VLAN.
- Support registration on MyVigor to obtain related services.
- Able to be managed by certain Vigor routers by switch management (SWM).

Improvement

- Corrected: An issue with CPU overload caused by multicast streaming packets.
- Corrected: An issue with the failure to send NTP packets out without a DNS server IP address.
- Corrected: An issue with the compatibility of the SFP module DrayTek ES-T2-RJ45 (10/100/1000M).
- Corrected: An issue with a configuration error related to the 10G SFP port number in Advanced>>Port Mirror.
- Corrected: Issues with the edge port change and the system reboot, caused by the enabled/disabled STP settings.

Known Issue

- The SFP port link status might be shown incorrectly on the Dashboard if zooming the browser's pages.
- The default password is unable to be changed if the web user interface is translated into languages other than English.